




कार्यालय सहायक अभियन्ता (षष्ठम)
प्रान्तीय खण्ड, लो0नि0वि0 रुद्रपुर(ऊधमसिंह नगर)
Email address- eepwdrudrapur@gmail.com

No. २२ / 1 C / कैम्प

Date 06/02/2024

Building Safety Certificate

This is certified that the school building of MAHRISHI VIDYA MANDIR Sihimla Pistor Kichha Rod Rudrapur, Udham Singh Nagar, Uttarakhand was inspected by me on 06-02-2024. The building of school found structurally sound and it is in good condition . It has been observed on visual inspection that existing building of the said school seems to be safe at present under normal circumstances for the year 2023-2024


06/02/24
सहायक अभियन्ता
प्रान्तीय खण्ड, लो0 नि0 वि0
रुद्रपुर